



< Actual Slab Orientation >

CYGNUS

QUARTZITE

BRAZIL




CYGNUS

Description

Cygnus is extracted in the region of Minas Gerais, Brazil. Bronze, cedar, copper and coffee hues are dominant in Cygnus's coloration, and it is spotted with ivory and black. Blocks are cut in a way to feature its depth's tridimensional effect, an extraordinary look unmatched by any other natural stone on the market.

An activator is factory-applied to darken this quartzite, and once it dissipates, its true colors will enhance the pale grey flecks present in the stone. In order to maintain a darker coloration, a sealer should be applied every 6 to 8 months or as needed.

In the course of the polishing process, an epoxy resin is applied to the stone's surface to fill part of its porosity (or pores) and natural cracks that may be apparent. This has no incident on the durability, the maintenance or the beauty of the natural stone. It is possible that certain pores are too small to contain efficiently the resin, and reopen during the finishing stages. However, this does not affect the stone's quality or beauty. Such as it is the case with many natural stones, it is recommended to apply a sealer to extend its beauty through time.



Available Finishes


Polished 


Antique 


Applications

- Counters
- Fireplace Contours
- Flooring
- Full-size backsplash
- Interior furniture
- Podium Bath Contours
- Shower Base
- Sinks
- Walls

Characteristics

Scratch Resistant 

Heat Resistant 

 Stain Protection

Recommended